



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36522

Inspection Report

Project Name: 1645 Pam Circle ~ COBI
Address: 1645 Pam Circle ~ COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400134.0000

Date: 04/15/2014 Any am
Permit No.: 2014-03-022
Lot No.:
Contact: Matt Harper at 407-812-6638

Scope of Inspection: Final window inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362