



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36496

Inspection Report

Project Name: 2534 Oak Island Point Road ~ COBI
Address: 2534 Oak Island Point Road ~ COBI ,Belle Isle,
Client: Orange County, FL
City of Belle Isle
ProjectNo.: 0115.1400016.0000

Date: 04/14/2014 Any any
Permit No.: 2014-04-020
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW app for permit to demo decorative stucco from rear columns

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240