



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36816

Inspection Report

Project Name: 2534 Oak Island Point Road ~ COBI

Date: 04/29/2014 Any pm

Address: 2534 Oak Island Point Road ~ COBI ,Belle Isle,

Permit No.: 2014-04-020

Client: Orange County, FL
City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400016.0000

Contact: Jason Cross at 407-925-6110

Scope of Inspection: FINAL demo inspection (call ahead as there is a gate code)

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362