

UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maggie Boulevard Orlando, FL 32811

Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36542

Inspection Report

Project Name: 2819 Nela Avenue - COBI	Date: 04/16/2014 Any am
Address: 2819 Nela Avenue - COBI ,Belle Isle, Orange	Permit No.: 2014-10-037
County, FL 32812 Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1300549.0000	Contact: Melissa Roman at 407-282-9552
Scope of Inspection: Final low voltage inspection ~ LOCK BOX CODE=2007	
Inspection Type: See Scope	
Disposition of Inspection: Pass	
Comments:	

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362

sis A Colon