



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36561

Inspection Report

Project Name: 3909 Isle Vista Ave - COBI
Address: 3909 Isle Vista Ave - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1300166.0000

Date: 04/28/2014 Any any
Permit No.: 2014-04-025
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: CONCURRENT REVIEW: app for screen enclosure 10' x 38'.

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

04/28/2014 Angel completed review on 04/21/14 however work order was never resulted as Complete.

Collina Gast

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240