



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36444

Inspection Report

Project Name: 3921 Isle Vista Avenue - COBI
Address: 3921 Isle Vista Avenue - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400077.0000

Date: 04/11/2014 Any any
Permit No.: 2014-03-005
Lot No.:
Contact: Katlynn Staats at 321 441 2300

Scope of Inspection: Dry-in roof inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362