



# UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36708

## Inspection Report

Project Name: 3921 Isle Vista Avenue - COBI

Date: 04/23/2014 Any am

Address: 3921 Isle Vista Avenue - COBI ,Belle Isle, Orange

Permit No.: 2014-03-023

Client: <sup>County, FL</sup>  
City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400077.0000

Contact: Kelli Tremblay at 407 960 1601

Scope of Inspection: Mechanical Rough Inspection

**Inspection Type:** See Scope

**Disposition of Inspection:** Pass

### Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362