

## UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maggie Boulevard Orlando, FL 32811

Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36041

## **Inspection Report**

Project Name: 3927 Isle Vista Avenue ~ COBI	Date: 04/01/2014 Any any
Address: 3927 Isle Vista Avenue ~ COBI ,Belle Isle, Orange	Permit No.: 2014-01-019
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1300739.0000	Contact: Missy at 407 834 7100
Scope of Inspection: Pool Safety Inspection	
Inspection Type: See Scope	
Disposition of Inspection: Pass	
Comments:	

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Angel Perez, BN 5240

Mi faces