



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36084

Inspection Report

Project Name: 3927 Isle Vista Avenue ~ COBI
Address: 3927 Isle Vista Avenue ~ COBI ,Belle Isle, Orange
Client: ^{County, FL} City of Belle Isle
ProjectNo.: 0115.1300739.0000

Date: 04/02/2014 Any pm
Permit No.: 2014-11-002
Lot No.:
Contact: John Martin at 407-446-1933

Scope of Inspection: Sidewalk inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Donald Beckman, BN5123