



**UNIVERSAL ENGINEERING SCIENCES, INC.**

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

**Work Order No.36434**

**Inspection Report**

Project Name: 3927 Isle Vista Avenue ~ COBI  
Address: 3927 Isle Vista Avenue ~ COBI ,Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1300739.0000

Date: 04/10/2014 Any any  
Permit No.: 2014-12-002  
Lot No.:  
Contact: Tim at 407 448 1579

Scope of Inspection: FINAL plumbing inspection

**Inspection Type: See Scope**

**Disposition of Inspection: Pass**

**Comments:**

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362