



# UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36086

## Inspection Report

Project Name: 4100 Isle Vista Avenue ~ COBI

Date: 04/02/2014 Any any

Address: 4100 Isle Vista Avenue ~ COBI ,Belle Isle, Orange

Permit No.: 2014-01-024

Client: <sup>County, FL</sup>  
City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300755.0000

Contact: Missy at 407-834-7100

Scope of Inspection: Underground electrical inspection for pool

**Inspection Type:** See Scope

**Disposition of Inspection:** Pass

### Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Donald Beckman, BN5123