



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36389

Inspection Report

Project Name: 4100 Isle Vista Avenue ~ COBI

Date: 04/09/2014 Any am

Address: 4100 Isle Vista Avenue ~ COBI ,Belle Isle, Orange

Permit No.: 2014-11-013

Client: ^{County, FL}
City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300755.0000

Contact: John Martin at 407 446 1933

Scope of Inspection: Sidewalk inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362