



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maggie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36728

Inspection Report

Project Name: 5107 Oak Island Road

Date: 04/23/2014 Any any

Address: 5107 Oak Island Road ,Belle Isle, Orange County,

Permit No.: 2014-04-044

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400207.0000

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW irrigation app for plumbing permit 52 heads

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240