



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36106

Inspection Report

Project Name: 5205 Oak Island Road ~ COBI
Address: 5205 Oak Island Road ~ COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400143.0000

Date: 04/03/2014 Late am
Permit No.: 2014-03-028
Lot No.:
Contact: Robert Batson at 407 423 7570

Scope of Inspection: IN progress roof inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Danny Hawkins, BN5278