



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36125

Inspection Report

Project Name: 5205 Oak Island Road ~ COBI
Address: 5205 Oak Island Road ~ COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400143.0000

Date: 04/04/2014 Any any
Permit No.: 2014-03-028
Lot No.:
Contact: Cynthia at 407 555 1212

Scope of Inspection: FINAL roofinspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Danny Hawkins, BN5278