



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36470

Inspection Report

Project Name: 5314 Chiswick Circle - COBI
Address: 5314 Chiswick Circle - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1300700.0000

Date: 04/14/2014 Any any
Permit No.: 2013-09-069
Lot No.:
Contact: Linda Emery at 407-488-5181

Scope of Inspection: FINAL door inspection Store contact Julie: 407 382 2211 x810. Permit has been lost, nothing to sign.

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362