



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36438

Inspection Report

Project Name: 5327 Hawford Circle - COBI
Address: 5327 Hawford Circle - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1300356.0000

Date: 04/10/2014 Any any
Permit No.: 2014-04-017
Lot No.:
Contact: Susan Manchester at 407 851 8161

Scope of Inspection: REVIEW plumbing permit for re-pipe

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240