



**UNIVERSAL ENGINEERING SCIENCES, INC.**

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

**Work Order No.36639**

**Inspection Report**

Project Name: 5327 Hawford Circle - COBI

Date: 04/24/2014 Any pm

Address: 5327 Hawford Circle - COBI ,Belle Isle, Orange

Permit No.: 2014-04-017

Client: <sup>County, FL</sup> City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300356.0000

Contact: Bill Bergman at 773 301 8132

Scope of Inspection: Final plumbing inspection for repipe (requesting Luis NOT be the assigned inspector)

**Inspection Type: See Scope**

**Disposition of Inspection: Pass**

**Comments:**

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240