



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maggie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36683

Inspection Report

Project Name: 5337 Jade Circle - COBI

Date: 04/22/2014 Any any

Address: 5337 Jade Circle - COBI ,Belle Isle, Orange County,

Permit No.: 2014-04-036

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400200.0000

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW App for Mechanical permit - One 4- ton unit

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Angel Perez, BN 5240