



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36059

Inspection Report

Project Name: 6608 Saint Partin Place - COBI
Address: 6608 Saint Partin Place - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400159.0000

Date: 04/02/2014 Any am
Permit No.: 2014-04-008
Lot No.:
Contact: Michael Manos at 352-442-5379

Scope of Inspection: Roof deck nailing / flashing inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Danny Hawkins, BN5278