



**UNIVERSAL ENGINEERING SCIENCES, INC.**

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

**Work Order No.36115**

**Inspection Report**

Project Name: 6608 Saint Partin Place - COBI  
Address: 6608 Saint Partin Place - COBI ,Belle Isle, Orange  
Client: <sup>County, FL</sup> City of Belle Isle  
ProjectNo.: 0115.1400159.0000

Date: 04/03/2014 Any am  
Permit No.: 2014-04-008  
Lot No.:  
Contact: Mike Manos at 352 442 5379

Scope of Inspection: Roof in progress inspection

**Inspection Type: See Scope**

**Disposition of Inspection: Fail**

**Comments:**

04/04/2014 Per Danny Hawkins: paperwork locked in garage - could not access to sign off.

Susan Manchester

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Danny Hawkins, BN5278