



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.36143

Inspection Report

Project Name: 6806 Seminole Avenue ~ COBI
Address: 6806 Seminole Avenue ~ COBI ,Belle Isle, Orange
Client: ^{County, FL} City of Belle Isle
ProjectNo.: 0115.1400171.0000

Date: 04/08/2014 Any am
Permit No.:
Lot No.:
Contact: Robyn Winters at 407-497-1868

Scope of Inspection: Meet Code Enforcement officer at vacant lot on the corner of Nela Ave & Seminole Ave to inspect abandoned trailer ~ call 30mins prior so she can meet you.

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

04/08/2014 Examined aboandoned trailer with Robyn from Code Enforcement. Photos are available. Danny Hawkin
Found the trailer as listed below
1. Structure is unsecured.windows and doors broken
2. No running water
3. No electricity
4. Signs of someone living there
5. signs of animals in and under trailer
6. raw sewage in toilets

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Danny Hawkins, BN5278