



**UNIVERSAL ENGINEERING SCIENCES, INC.**

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

**Work Order No.36782**

**Inspection Report**

Project Name: 7208 Seminole Drive - COBI  
Address: 7208 Seminole Drive - COBI ,Belle Isle, Orange  
Client: <sup>County, FL</sup> City of Belle Isle  
ProjectNo.: 0115.1400112.0000

Date: 04/24/2014 Any any  
Permit No.: 2014-11-001  
Lot No.:  
Contact: Phil Sutherland at 407 509 3885

Scope of Inspection: Investigate boat dock construction without a permit; if evidence of construction is present, issue SWO, report results on work order & upload pictures into ShareFile.

**Inspection Type:** See Scope

**Disposition of Inspection:** Fail

**Comments:**

04/24/2014 Investigated work at premises found boat dock was under construction and material on site was still there but no workers on site at this time. Also found work being done on rear of porch at home found new slab has been poured, and roof over deck being constructed with new decking and beams installed. Issued SWO took 40 pictures and uploaded to ShareFile. Luis Colon

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362