



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49331

Inspection Report

Project Name: 1717 Pam Circle ~ COBI

Address: 1 Franconia Drive ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500081.0000

Scope of Inspection: Roof Deck Nailing / Dry-in / Flashing Inspection

Inspection Type: See Scope

Date: 04/09/2015 Any any

Permit No: 2015-03-003

Lot No.:

Contact: Cynthia Waters at 407-423-7570

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489