



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.49293

Inspection Report

Project Name: 1307 E. Wallace Street ~ COBI
Address: 1307 E. Wallace Street ~ COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1300623.0000

Date: 04/07/2015 Any any
Permit No.: 2015-04-017
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW app for solar for electricity

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

04/07/2015 Need cut sheets for the inverter and the other associated electrical equipment. Also need installation details for the solar panels that has been prepared by a Florida design professional.

Ralph Jones

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Ralph Jones, BN1437