



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49342

Inspection Report

Project Name: 1614 Nela Avenue ~ COBI

Address: 1614 Nela Avenue ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400417.0000

Scope of Inspection: Final Electrical Inspection

Inspection Type: See Scope

Date: 04/09/2015 Any any

Permit No: 2015-01-019

Lot No.:

Contact: Tina at 407-709-1055

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/09/2015	House locked. Contractor did not return my calls. Not able to complete inspection.	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489