



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49442

## Inspection Report

Project Name: 1717 Pam Circle ~ COBI

Address: 1717 Pam Circle ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500081.0000

Scope of Inspection: Final Roof Inspection

Inspection Type: See Scope

Date: 04/13/2015 Any any

Permit No: 2015-03-003

Lot No.:

Contact: Cynthia Waters at 407-423-7570

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362