



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50223

Inspection Report

Project Name: 1919 Hoffner Avenue - COBI

Date: 04/27/2015 Any any

Address: 1919 Hoffner Avenue - COBI ,Belle Isle, Orange County, FL

Permit No: 2015-01-012

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300052.0000

Contact: Darrin Larsen at 407-463-5787

Scope of Inspection: Final Building Inspection for wall


Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362



Luis A. Colon