



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49976

## Inspection Report

Project Name: 2323 McCoy Road ~ COBI (multi-family)

Address: 2323 McCoy Road ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400403.0001

Scope of Inspection: Bldg. 7, Unit 714 - Framing Inspection

Inspection Type: **See Scope**

Date: 04/21/2015 Any any

Permit No: 2015-12-050

Lot No.:

Contact: Sunia Piermont at 407-947-4968

**Disposition of Inspection:** Partial Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/21/2015	Partial ONLY, 2nd floor ceiling LVL,connectors and supporting built up columns ONLY. Engineers letter required for microlam substitution of 4 x 2x8 instead of 3 LVL.	Leslie Rutherford

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564