



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49765

Inspection Report

Project Name: 2509 Nela Avenue ~ COBI

Address: 2509 Nela Avenue ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400518.0000

Date: 04/16/2015 Any any

Permit No: 2015-04-026

Lot No.:

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW plumbing app for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Richard Olds, BN 4406