



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49407

Inspection Report

Project Name: 2523 Kissam Court ~ COBI

Date: 04/14/2015 Any am

Address: 2523 Kissam Court ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-02-040

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400447.0000

Contact: Ryan Holland at 407-509-9608

Scope of Inspection: Pool Safety Inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564