



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50139

Inspection Report

Project Name: 2523 Kissam Court ~ COBI

Date: 04/24/2015 Any any

Address: 2523 Kissam Court ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-02-040

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400447.0000

Contact: Ryan Holland at 407-509-9608

Scope of Inspection: Final Building Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564