



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49981

Inspection Report

Project Name: 2549 Oak Island Pointe ~ COBI

Date: 04/22/2015 Any any

Address: 2549 Oak Island Pointe ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-04-031

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500625.0000

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW building app for Cabana & screening wall (cannot email - plans too large)

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

| <u>Task Date</u> | <u>Task Note</u> | <u>User Name</u> |
|------------------|--|------------------|
| 04/22/2015 | Plan review notes provided to permit tech. | Ralph Jones |

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Ralph Jones, BN1437