



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50059

## Inspection Report

Project Name: 2705 Nela Avenue ~ COBI

Date: 04/22/2015 Any am

Address: 2705 Nela Avenue ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-10-012

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400335.0000

Contact: Rafael Valle at 321-202-0478

Scope of Inspection: Exterior Frame Inspection for walkway

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489