



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49942

Inspection Report

Project Name: 3007 Cullen Lake Shore Drive - COBI

Address: 3007 Cullen Lake Shore Drive - COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500002.0000

Scope of Inspection: Final Plumbing Inspection

Inspection Type: See Scope

Date: 04/20/2015 Any any

Permit No: 2015-02-012

Lot No.:

Contact: Sean Abernethy at 386-848-3561

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/20/2015	FPC 424.3 ,tempering valve required at bath-tub	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362