



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49988

Inspection Report

Project Name: 3101 Trentwood Boulevard - COBI

Address: 3101 Trentwood Boulevard ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300064.0000

Date: 04/20/2015 Any any

Permit No: 2014-05-035

Lot No.:

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW of plans and phone consult for boat dock

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Angel Perez, BN 5240