



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.48979

Inspection Report

Project Name: 3417B Warren Park Road - COBI
Address: 3417 Warren Park Road - COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1500022.0000

Date: 04/01/2015 Any am
Permit No.: 2015-01-033
Lot No.:
Contact: Rich Randolph at 407-702-3014

Scope of Inspection: Electrical Rough-in Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Ralph Jones, BN1437