



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49938

## Inspection Report

Project Name: 3430 Cullen Lake Shore Drive ~ COBI	Date: 04/20/2015 Any am
Address: 3430 Cullen Lake Shore Drive ~ COBI ,Belle Isle, Orange County, FL	Permit No: 2015-02-002
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1400561.0000	Contact: Arthur Kozik at 407-497-8740
Scope of Inspection: Final Demolition Inspection	
Inspection Type: See Scope	

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/20/2015	work not ready at this time	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362