



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49937

Inspection Report

Project Name: 3430 Cullen Lake Shore Drive ~ COBI

Address: 3430 Cullen Lake Shore Drive ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400561.0000

Scope of Inspection: Plumbing rough-in Inspection

Inspection Type: See Scope

Date: 04/20/2015 Any am

Permit No: 2015-04-034

Lot No.:

Contact: Arthur Kozik at 407-497-8740

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362