



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49333

Inspection Report

Project Name: 3612 Saint Moritz Street ~ COBI

Date: 04/09/2015 Any pm

Address: 3612 Saint Moritz Street ~ COBI ,Belle Isle, Orange County,
FL

Permit No: 2015-02-035

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500058.0000

Contact: Chuck Hensel at 407-467-7926

Scope of Inspection: Final Building Inspection of aluminum wall addition to enclose lanai

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489