



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50313

Inspection Report

Project Name: 4106 Isle Vista Ave ~ COBI

Date: 04/28/2015 Any any

Address: 4106 Isle Vista Ave ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-10-017

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400431.0000

Contact: Katlynn Staats at 321-441-2300

Scope of Inspection: Final Roof Inspection for house

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564