



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50061

Inspection Report

Project Name: 4124 Kandra Drive ~ COBI

Date: 04/22/2015 Any any

Address: 4124 Kandra Drive ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-04-030

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500624.0000

Contact: Tom Ringler at 407-678-9721

Scope of Inspection: Roof Deck Nailing / Dry-in / Flashing Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489