



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49374

Inspection Report

Project Name: 4948 Oak Island Road - COBI

Date: 04/10/2015 Late am

Address: 4948 Oak Island Road - COBI ,Belle Isle, Orange County, FL

Permit No: 2015-04-016

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500014.0000

Contact: Clarence Tibbs at 407-509-2733

Scope of Inspection: Underground Electrical Inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489