



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50227

Inspection Report

Project Name: 4948 Oak Island Road - COBI

Date: 04/24/2015 Any any

Address: 4948 Oak Island Road - COBI ,Belle Isle, Orange County, FL

Permit No: 2015-04-057

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500014.0000

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW app for NEW roof for porch extension

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Ralph Jones, BN1437