



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 50258

Inspection Report

Project Name: 4948 Oak Island Road - COBI

Date: 04/27/2015 Any any

Address: 4948 Oak Island Road - COBI ,Belle Isle, Orange County, FL

Permit No: 2015-04-057

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500014.0000

Contact: Rob Ducharme at 321-303-0766

Scope of Inspection: Roof Dry-in / Flashing Inspection


Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362



Luis A. Colon