

UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maggie Boulevard Orlando, FL 32811

Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.49255

Inspection Report

04/08/2015 Any pm Project Name: 4948 Oak Island Road - COBI Date: Address: 4948 Oak Island Road - COBI ,Belle Isle, Orange Permit No.: 2015-01-027 County FL City of Belle Isle Client: Lot No .: 0115.1500014.0000 Luddy Goetz at 321-230-0199 ProjectNo.: Contact:

Scope of Inspection: Framing Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

04/08/2015 Floor joists not blocked at their ends or over supports as required by FBC 2808.8. Plans

Ralph Jones

were not available at the job site.

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Ralph Jones, BN1437

Raphhljones