



# UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.48964

## Inspection Report

Project Name: 5018 Monet Avenue ~ COBI

Date: 04/01/2015 Any am

Address: 5018 Monet Avenue ~ COBI ,Belle Isle, Orange

Permit No.: 2015-12-025

Client: <sup>County, FL</sup>  
City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400557.0000

Contact: Jerry at 407 509 0370

Scope of Inspection: Framing inspection

**Inspection Type:** See Scope

**Disposition of Inspection:** Pass

### Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362