



UNIVERSAL ENGINEERING SCIENCES, INC.

3532 Maqqie Boulevard
Orlando, FL 32811
Phone: 407-581-8161 Fax: 407-581-0313

Work Order No.49047

Inspection Report

Project Name: 5018 Monet Avenue ~ COBI
Address: 5018 Monet Avenue ~ COBI ,Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400557.0000

Date: 04/02/2015 Any any
Permit No.: 2015-03-013
Lot No.:
Contact: Jessica at 352-459-7599

Scope of Inspection: Roof Covering in-progress Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362