



**UNIVERSAL ENGINEERING SCIENCES, INC.**

3532 Maqqie Boulevard  
Orlando, FL 32811  
Phone: 407-581-8161 Fax: 407-581-0313

**Work Order No.48907**

**Inspection Report**

Project Name: 5107 Gramont Avenue ~ COBI  
Address: 5107 Gramont Avenue ~ COBI ,Belle Isle, Orange  
County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1500160.0000

Date: 03/31/2015 Any am  
Permit No.: 2015-03-020  
Lot No.:  
Contact: Walter Delgado at 321-276-4123

Scope of Inspection: Final Electrical Inspection

**Inspection Type: See Scope**

**Disposition of Inspection: Pass**

**Comments:**

I hereby affirm that to the best of my knowledge and believe, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector : Luis Colon, BN3362