



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 49763

Inspection Report

Project Name: 5126 St. Germain Avenue - COBI
Address: 5126 St. Germain Avenue ,Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1300159.0000

Date: 04/15/2015 Any any
Permit No: 2015-04-029
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW electrical permit app to replace sub-panel

Inspection Type: See Scope

Disposition of Inspection: Complete

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/15/2015	Approved per Richard.	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Richard Olds, BN 4406